

N7454Y

REPAIR & MAINTENANCE HISTORY

JPI-760 Engine & Fuel Flow Monitor	October-98
Gear Alert System	May-99
Interior Refurbish	February-00
Lo-Presti Speed Mods	February-00
Right Engine OH	June-01
Exterior Paint	September-01
Garmin GTX-327 Transponder	April-02
WX-1000 Stormscope	April-02
Fuel Bladders (Rt. Main/Lt. Aux.)	July-02
Garmin GMA-340 Audio Panel	April-03
Garmin GNS-430 GPS	April-03
PS Intercom	April-03
Fuel Bladders (Lt. Main/Rt. Aux.)	May-03
Digital Tachs	June-03
Garmin GDL-49 Weather Link	June-03
Props/Governors OH (Tach 5764)	August-04
Vertical Card Compass (new)	June-05
Reiff Engine Preheaters	October-05
Gear Inspection - 1000 hr.	October-05
Vacuum Pump - Lt. Eng. (new)	March-06
Airspeed Indicator (new)	May-06
Lt. Engine - Factory Reman	May-06
Vacuum Manifold (OH)	May-06
Manifold Pressure Gauge (OH)	June-06
Turn Coordinator (new)	July-06
Century 2000 AP (OH)	July-06
Attitude Gyro (OH)	February-07
Altitude Encoder (new)	March-07
Heater OH	November-07
Replace Gear Cables	June-09
Replace Stabilator Horn Assembly per Piper SB	November-10
Last Annual	May-10
Current TT	6270